Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/18018UE-1830/1

Work Order Type: Weatherization

Audit Name: Audit (247)

CLIENT INFORMATION

Client Name: Address:

Client ID: 18018UE-1830

Alt. Client ID: Carter

<u>AGENCY INFORMATION</u>

Agency: Upper East Tennessee Human Development Agency Agency Phone: 246-6180

Address: 301 Louis Street Fax:

> Kingsport, TN 37662 Email Address: howardh@uethda.org

Agency Contact: Hoard, Howard Work Phone: (423) 246-6180

> **Cell Phone: Email Address:**

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

Client owns a trailer house house has been vacant for many moth all window sill are rotten client has rotten eve vent 60 l. ft sq ft is 28' x 70'= 1960 the dusts are leaky around 2nd bath and living rm. Kitchen and materbath leaky 16.69 pa. Need to add attic and repair ceiling 120 sq ft. approx.

The are under home wet creek runs beside home have to access other side of crawlspace

front door hollow underneath you can se bottom side from that locaton approx area 3' of rehab main door has multiple issue with light coming in.

Client has multiple std blubs

exhaust.

Client Name: Client ID: 18018UE-1830 Alt. Client ID: Carter

Work Order (Bid Form)

Report Run On: 4/13/2012

DOE Weatherization Assistant Work Order Name: WO/18018UE-1830/1 Version 8.6.0

Page 1 of 9

Measures

| | Measure 1 Infilt | ration Redctn | | | Componen | ı | nspected | | |
|---|------------------|--|----------------|--------|--------------|-------|----------|------------------|-------|
| C | comment Caulk10 | windows | | | | | | | |
| | | | | | Estimated | | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Labor | install caulk | Each | 10 | | | | | |
| 1 | Miscellaneous Su | Infiltration Reduction (caulk windows) | Each | 10 | | | | | |
| 2 | Miscellaneous Su | Seal ducts leaky high 16pa. | Each | 9 | | | | | |
| 2 | Labor | mastic Ducts | Each | 9 | | | | | |
| 3 | Miscellaneous Su | check for gaps in the truck lines | Linear Foot | 1 | | | | | |
| 3 | Lighting | check for hole and gaps | Hour | 2 | | | | | |
| (| Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | | | | | |

| | Measure 2 DWH | H Tank Insulation | | | Componen | its | | | Inspected |
|---|------------------|-----------------------|-------|--------|--------------|-------|-----|------------|-----------|
| C | Comment | | | | | | | | |
| | | | | | Estimated | 1 | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Hot Water Equip | DHW Tank Insulation | Each | 1 | | | | | |
| 1 | Labor | DHW Tank Insulation | Each | 1 | | | | | |
| (| Other Detail | | | | | | 1 | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] . | Sub Total: | |
| | Field Notes: | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| | <i>Measur</i> e 3 Ligh | nting Retrofits | | | Components LT1,LT2,LT3,LT4 Inspec | | | | | |
|---|------------------------|-------------------------------------|--------------|-----------|-----------------------------------|-------|--------|------------|-------|--|
| C | Comment | | | | | | | | | |
| | | | | Estimated | | | Actual | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 | Lighting | Compact Fl 13 Watt (Kicthen) | Each Lamp | 2 | | | | | | |
| 1 | Labor | Compact Fl 13 Watt | Each Lamp | 2 | | | | | | |
| 2 | Labor | Compact Fl 13 Watt | Each Lamp | 3 | | | | | | |
| 2 | Lighting | Compact Fl 13 Watt (Living Rm) | Each Lamp | 3 | | | | | | |
| 3 | Lighting | Compact Fl 13 Watt (Bedroom) | Each Lamp | 2 | | | | | | |
| 3 | Labor | Compact Fl 13 Watt | Each Lamp | 2 | | | | | | |
| 4 | Lighting | Compact Fl 15 Watt Flood (Bedroom) | Each Lamp | 2 | | | | | | |
| 4 | Labor | Compact Fl 15 Watt Flood | Each Lamp | 2 | | | | | | |
| C | Other Detail | | | | | _ | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] ; | Sub Total: | | |
| | Field Notes: | | | | | | | | | |

| | | | | Componen | ts | | | Inspecte |
|--|---|----------------------|----------------------|---------------------|----------|-----|------------------|--------------|
| | | | | Estimated | <u> </u> | | Actual | |
| 1 Insulation DH | scription / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| | HW Pipe Insulation | Each | 1 | | | | | |
| 1 Labor DH | HW Pipe Insulation | Each | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | , | Sub Total: | |
| | D 20 | | | | | | | |
| Measure 5 Attic Ins Comment | s. K-30 | | | Componen Estimated | | | | Inspecte |
| Comment | | Units | Qty | Estimated Unit Cost | | Qty | Actual Unit Cost | Inspecte |
| Comment # Material / Labor De 1 Labor Att | escription / Comment tic Insulation - Blown perglass - R-30 | <i>Units</i> SqFt | | Estimated | 1 | Qty | Actual | |
| Comment # Material / Labor De 1 Labor Att Fib. 1 Insulation Att | escription / Comment tic Insulation - Blown | | Qty | Estimated | 1 | Qty | Actual | |
| Comment # Material / Labor De 1 Labor Att Fib 1 Insulation Att | escription / Comment tic Insulation - Blown perglass - R-30 tic Insulation - Blown | SqFt | Qty 1960 | Estimated | 1 | Qty | Actual | |
| Comment # Material / Labor De 1 Labor Att Fib 1 Insulation Att | escription / Comment tic Insulation - Blown perglass - R-30 tic Insulation - Blown | SqFt | Qty 1960 | Estimated | 1 | Qty | Actual | |
| Comment # Material / Labor De 1 Labor Att Fib 1 Insulation Att | escription / Comment tic Insulation - Blown perglass - R-30 tic Insulation - Blown | SqFt | Qty 1960 1960 | Estimated | 1 | | Actual | |

| | terial / Labor | | | | | | | | |
|-------------|------------------|---|-------|--------|-----------------------|-----------|-----|-------------|-----------|
| | torial / Labor | | | | Estimated | | | Actual | |
| 1 Ins | teriai / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| | sulation | Floor Insulation - Fiberglass Batts - R-19 | SqFt | 1960 | | | | | |
| 1 Lat | bor | Floor Insulation - Fiberglass Batts - R-19 | SqFt | 1960 | | | | | |
| Other | r Detail | | | | | | , | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| Mea Comi | | Monitor is Needed | | | Componen Estimated | ts | | l Actual | Inspected |
| # Mat | terial / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Lab | | Labor | Each | 1 | | 7 0 0 0 1 | | | |
| 1 He | ealth and Safety | CO monitor | Each | 1 | | | | | |
| Other | r Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| Fiel | ld Notes: | | | | | | | | |
| | | | | | | | | | |

| | Measure 8 Reha | b eaves | | | Componer | nts | | I | nspected | |
|---|--------------------------|---|----------------|-----------|--------------|-------|--------|------------|----------|--|
| C | Comment 3 section | of eave need repair | | | | | | | | |
| | | | | Estimated | | | Actual | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 | Construction Mate | need to repair eave 20 Ln Ft section | Each | 1 | | | | | | |
| 1 | Labor | repair eave | Linear Foot | 20 | | | | | | |
| 2 | Labor | repair eave | Linear Foot | 25 | | | | | | |
| 2 | Construction Mate | need to repair eave 25 Ln Ft section | Each | 1 | | | | | | |
| 3 | Cooling Equipmen | Repair 3rd section of eave 25 Ln Ft section | Each | 1 | | | | | | |
| 3 | Labor | repair eave | Linear Foot | 25 | | | | | | |
| (| Other Detail | | | | | | | | | |
| L | | | | | | | | | | |
| | | | | | | | | | | |
| _ | | | | Measur | e Sub Total: | | | Sub Total: | | |
| | Field Notes: | | | | | | | | | |

| | air (10) window sashes | | | Componen | ts | | | Inspected |
|--|--|----------------------|--------|---------------------|----------|-----|------------------|-----------------|
| Comment | | | | | | | | |
| | | | | Estimated | <u> </u> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Unspecified | Misc Material | Each | 10 | | | | | |
| 1 Labor | repair window Facing for 10 windows | Each | 10 | | | | | |
| 2 Miscellaneous Su | caulk inside of windows | Each | 10 | | | | | |
| 2 Labor | install caulk to insie of windows | Each | 10 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | | Sub Total: | |
| | | | | | | | | |
| Measure 10 Rep | place front main door | | | Componen | | | | Inspected |
| Comment | | Units | Ofv | Estimated | <u> </u> | Qfv | Actual | |
| _ | Description / Comment Misc Material | <i>Units</i> Each | Qty | - | | Qty | | Inspected Total |
| Comment# Material / Labor1 Unspecified | Description / Comment Misc Material | Each | 1 | Estimated | <u> </u> | Qty | Actual | |
| Comment # Material / Labor | Description / Comment | | | Estimated | <u> </u> | Qty | Actual | |
| Comment# Material / Labor1 Unspecified | Description / Comment Misc Material remove and replace door (main) w steel | Each | 1 | Estimated | <u> </u> | Qty | Actual | |
| # Material / Labor 1 Unspecified 1 Labor | Description / Comment Misc Material remove and replace door (main) w steel | Each | 1 | Estimated | <u> </u> | Qty | Actual | |
| # Material / Labor 1 Unspecified 1 Labor | Description / Comment Misc Material remove and replace door (main) w steel | Each Each | 1 | Estimated Unit Cost | <u> </u> | | Actual Unit Cost | |
| # Material / Labor 1 Unspecified 1 Labor Other Detail | Description / Comment Misc Material remove and replace door (main) w steel | Each Each | 1 | Estimated | <u> </u> | | Actual | |
| # Material / Labor 1 Unspecified 1 Labor | Description / Comment Misc Material remove and replace door (main) w steel | Each Each | 1 | Estimated Unit Cost | <u> </u> | | Actual Unit Cost | |

| | <i>Measure</i> 11 Smo | ke Detector is Needed | Components | | | | | | Inspected | |
|---|-----------------------|-----------------------|------------|-----------|--------------|-------|------|------------|-----------|--|
| C | omment | | | | | | | | | |
| | | | | Estimated | | | | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 | Labor | Labor | Each | 1 | | | | | | |
| 1 | Health and Safety | Smoke detector | Each | 1 | | | | | | |
| C | Other Detail | | | | 1 | | 1 | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | | |
| | Field Notes: | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| L | | | | | | | | | | |
| | | | Work Or | der Gra | nd Total: | | Gran | d Total: | | |